



10700 Toebben Drive  
 Independence, KY 41051  
 Phone 859-448-2300  
 Fax 859-448-2333

# ESTIMATE

Page No

1

**Customer No**

3096

**Estimate No**

204285

**Estimate Date**

12/13/2021

**Project No**

P26594S03

**Estimate Status**

NEW ESTIMATE

**Valid Thru**

1/12/2022

**Salesperson**

Barry Becker

**Bill To:**

Town Branch WWTP  
 301 Jimmie Campbell Drive  
 Lexington, KY 40504 US

**Ship to:**

Town Branch WWTP  
 301 Jimmie Campbell Drive  
 Lexington, KY 40504 US

Item No	Description	Unit price	Order Qty		Extended price
C5E-4/454 REBUILD	rebuild parts	\$22,881.14	1.00	EA	\$22,881.14
BBAL	Bowl Balancing	\$1,800.00	1.00	EA	\$1,800.00
SBAL	Scroll Balancing	\$1,800.00	1.00	EA	\$1,800.00
SIMP GEAR SP 4.12	rebuild of SP 4.12 gear	\$6,610.00	1.00	EA	\$6,610.00
DCI	Disassembly, Cleaning, Inspect	\$100.00	16.00	HR	\$1,600.00
ST	Straight Time	\$100.00	43.00	HR	\$4,300.00

Estimate total may not reflect miscellaneous charges, freight or sales tax

Total price

\$38,991.14