| Page 2 of 2 | | | |
|--|--|-------------------------|--------|
| JUSTIFICATION FOR CHANGE | | PROJECT: MNA-5 D, E & F | |
| | | RESOLUTION NO. 471 | I-2014 |
| | | CHANGE ORDER: 1 | |
| 1. | Necessity for change: | | |
| 2. | Is proposed change an alternate bid?YesX_No | | |
| 3. | Will proposed change alter the physical size of the project? _X_YesNo | | |
| | If "Yes", explain. Several houses on Oak Hill Drive and Churchill Drive have, for years, experienced backyard flooding. This is primarily due to a low lying area in the middle of the block. The installation of a surface inlet in the back yard of 1023 Oak Hill Drive with a 15" Storm sewer line running through the rear lots of Oak Hill Drive can be installed with little impact to property and connected to the curb box on Park View Drive. Permanent Drainage Easements will be solicited from 1023, 1027 and 1031 Oak Hill Drive for the construction of said storm sewer line. | | |
| 4. | Effect of this change on other prime contractors: N/A | | |
| 5. | Has consent of surety been obtained?YesX_Not Necessary | | |
| 6. | Will this change affect expiration or extent of insurance coverage?Yes X_No | | |
| | If "Yes", will the policies be extended?YesNo | | |
| 7. | Effect on operation and maintenance costs: N/A | | |
| 8. Effect on contract completion date: N/A | | | |
| | | Mayor | Date |