R-602-2014 Original: R-548-2014 Contract # 227-2014

***************************************				Contract # 227-2014
L	EXINGTON-FAYETTE URBAN COUNTY	Date	June 29, 2016	
GOVERNMENT CONTRACT CHANGE ORDER Page 1 of 2 To (Contractor):		Project:	Senior Citizen Center Constructio	D T T
		Location:	Lexington	
	tractor): Design & Construction	Contract No.	227-2014	8.0
259 We	st Short Street	Original Contract Amt	\$8,882,900.00	
Suite 32 Lexingto	5 n, KY 40507	Cumulative Amount of Previous Change Orders	\$1,524,073.37	
		Percent Change - Previous Change Orders		17.16%
		Total Contract Amount Prior to this Change Order	\$10,406,973.37	
		Change Order No.	50	
dans of horse source , assuing about	You are hereby requested to comply with the following	changes from the contract plan	ns and specification;	
	Current Cha	nge Order		
Item No.	Description of changes-quantities, unit prices, change in completion date, etc	Decrease in contract price	Increase in contract price	
1	Furnish & install additional exit signage per PR 86		\$2,830.00	
2	Furnish & install a closure door @ security grille per PR 91			
			\$320.00	
	Total decrease	\$0.00		
THE STATE OF THE S	Total increase	Ψ0.00	\$3,150.00	
70.00	Net Amount of this Change Order	\$3,150.00	\$3,130,00	
	New Contract Amount Including this Change Order	\$10,410,123.37		
vertex	Percent Change - This Change Order	\$10,410,123.37		
	Percent Change - All Change Orders			0.04%
he time	provided for the completion in the contract and all	provisions of the contract will	apply hereto	17.19%
	mended by Joyce In	(Project Manager)		
ccepte	- And James Carlo	(Contractor)		
pprove		(Director)		
рргоче	()) the Coming	(Commissioner)	<u> </u>	
	ed by Asil 91-99	(Mayor or CAO)		

		Page 2 of 2				
		PROJECT: Senior Citizen Center Construction				
J	JUSTIFICATION FOR CHANGE	CONTRACT NO. 227-2014				
		CHANGE ORDER NO. 50				
1.	Necessity for change: Fire Marshal required needed at the security grille at the rece	quires 3 additional exit signs to be installed. A closure door is eption desk to conceal the door when the grille is not being used.				
2.	Is proposed change an alternate	e bid?Yes _X_No				
3.	. Will proposed change alter the physical size of the project?Yes _X_No					
	If "Yes", explain.					
4.	Effect of this change on other pri	rime contractors: N/A				
5.	Has consent of surety been obtain	ained? Yes X Not Necessary				
6.		or extent of insurance coverage?Yes _X_No				
	If "Yes", will the policies be exten					
7.	Effect on operation and maintena					
8.	Effect on contract completion dat	ite: 0 working days				
	fulf	Hamil				



Alternates
UIGG Replacement Senior Citizen Center
Lexington KY

A STATE OF THE

PR-96 Furnish and Install Additional Exit Signage per Proposal Request No. 86 - Revision #1 Lumish and Install Additional Exit Signage per Proposal Request No. 86	Quantity Units Hr Rep		Materials (Sales Lax Added Below :	enboorhaut :	
Foreigh and Install Admitional Exit Signage per Proposal Request No. 86 - AES	1 is	2.435 (3)		8.435	
		C.	()	2.81%	, d'-'
	Cost of	in-Place Construction (L	abor, Materials and	lif quipassay	1.39
	Į.	Mamilia Design and Con	istruction Overhead	Percentage =	147.89
		Overhead - M	amilia Design and	Construction	214.3
		Marritha Design and	Construction Profi	Percentage =	24/04
		Profit - M	amillia Design and	Construction =	107
		General Li	iability Insurance (C	Construction :	2
			Buider's Pr	sk Insurance ×	
	Performance and Payment Bon	id (Rate of \$9.40 per \$10	900 of Cost for \$0	\$2,500,000 1	175
	Performance and Payment Bond (Rate of	of \$8-15 per \$1000 of Co	est for \$2,500,000 -	\$5,000,0000	有病
	Performance and Payment Bond (Rate of \$7.20 per \$1000	of Cost for \$5,000	000 and 4(-) =	
		KY Surcharge on Pro-	ect Bonds (1.8% o	Bond Cost	
	.00	al Municipality Tax on Pr	oject Bonds (5% a	faquia Covin	
			Total Genst	nictor cor (2,630



Proposal Request Transmittal

Bir Prieses and the state of the control of the con

PROJECT:	LFUCG Senior Citizens' Center 201333	Burning State	6/16/2016
Section 1	Additional Exit Signs	wil two signs in g	PR-086
r + €	Proposal Request	The Artist of Artist	00998
· 安徽 (1957)	For Review and Response		Info Exchange

-17.041

4 Tak 4			
·艾克斯特.		表示	- · · · 公長要
Harding Dowell	EOP Architects	hdowell@eopa.com	(859) 231- 7538
#1			
V447		11-AL	m, Norm
Travis Harris	Marrillia Design and Construction	tharris@marrillia.com	

11/4 20

Created by: Harding Dowell Description:

Please provide pricing for three (3) additional exit signs per instruction from Building Inspection. The locations and types are as follows:

- 1 Act (1) exit sign at the southeast corner of the corndor in Administration (24). Select to the attached sketch for circuiting, but confirm final location prior to installation. Exit sign shall be type X2 from the originally submitted lighting package.
- 2 Add (1) exit sign above does 150A. Exit sign shall be Isolite Series 880 Grad 8A (sev economic but sheet). Face color shall be green. From a color shall be 85 island Aluminum. Service live shall be 20 order. In that colors a constant processing pracket to the horizontal multiple.

- above the door frame (10'-4 1/4" AFF), such that the exit sign hangs below the mullion, centered on the door. Install per manufacturer's recommendations.
- 3. Add (1) exit sign above door 151C. Exit sign shall be Isolite Series 880-G-20-BA (see enclosed cut sheet). Face color shall be green. Frame color shall be Brushed Aluminum. Service live shall be 20 years. Install universal mounting bracket to the horizontal mullion above the door frame (10'-4 1/4" AFF), such that the exit sign hangs below the mullion, centered on the door. Install per manufacturer's recommendations.

The Isolite Series 880 shall not be purchased until owner and building inspector approval is given.

Thanks.

Harding

DEFINISH FOR MOUNTAINS

1 6/16/2016 160616_PR-086_SKE-17.pdf

1 6/10/2016 illum exit sign 880 Series.pdf

250

Greg Brumagen

Brian Gravitt (Marrillia Design and Construction)
Jim Martin (Marrillia Design and Construction)
Josh Marrillia (Marrillia Design and Construction)
Rob Price (Marrillia Design and Construction)
Jessica Walker (LFUCG)
Joyce Thomas (LFUCG)
Martin Woodford (LFUCG)

(CMTA)

ADVANCED ELECTRICAL SYSTEMS, INC. (502) 962-1102 Fax (502) 962-8836 www.aeslou.com

POWERING THE FUTURE!

PO Box 36503 Louisville, KY 40233-6503 3312 Gilmore Industrial Bldg., Louisville, KY 40202

Change Order Summary

Time & Material Lump Sum. Description of	X				AES Change Order No. Contractor Date Revision AES Job No. Cust Contract No.	25 Advanced Elect June 27, 2016 1 12200	incal Sy	stems, inc.
Install 3 addition	nal exit sion	s ner drawi	ina		Cust. REP No.	086		·
Activity Descript		o per crawi	Material	Labor	Additional Days	3		
X2 \$150 Each		······································	\$ 150.00		SWO #	3		
Isolite Exit \$425	Each		\$ 850 00		Clarification:	Price Valid for 3	0.02.15	
See attached			\$ 93.7		200 mag 3011	Life Adire let 2	U Days	
l			\$.	s				
Subtotal Malena	al & Labor		3 1,093 7	\$ 1,276.00				
DEDUCT		······································	Material	Labor				
				\$0.00	1	BID SUMMARY	Y	
Subtotal Deduct			\$0.00	\$0.00				
Labor Rate Calo	ulations				Material Cost		S	1,093.71
Classification	uiations	0.00.056		11000 5101	Material Mark-up	0 0%	\$	
	~T	HOURS	RATE	LABOR COST	Subtotal		\$	1,093.71
1	ST		\$ 69.00		Tax	6%	\$	55.62
1	5.T		\$ 65.80		Total Material Costs		S	1,159,33
	ST ST	20 0	\$ 63.80 \$ 59.25					
					P			
. / 2	ist TH		\$ 43.80	*****	Sub Contractor Costs		5	*
	:m %-	0	\$ 94.00		Sub Contractor Mark-up		\$	-
**	The				Total Sub Contractor C	ost	\$	
	Plant Plant	0 0						
	** "Hi		\$ 80.75					
	H Dt	0			Equipment Rental		\$	
	07	3		*** *	Equipment Rental Mark	up 0%	ş	
	int.	3 3			Total Equipment Cost		3	
	5*		\$ 111.25 \$ 102.50					
	DI DI	0						
Safety	. .	0		40.00	Labor Cost		ş	1,276.00
Other		0	5 93.00	\$0.00	Markup on Labor Total Labor Cost		\$	
Subtotal Labor		20	······································	\$1,276.00	rotal Labor Cost		\$	1,276 00
Subcontractors	***************************************							
					Subtotal Add Cost		S	2 435.33
				1	No Bond		ŝ	4.400.00
				1	Total CO Add Cost		5	2 435,33
Subtotal Subcon	tractors	*****	**************************************	Ĭ .			L	
Equipment Rent	al (includin	g fax)		1	Material Deduct			
**************************************	***************************************		***************************************		Tax on Deduct Material	0.0%		
					Labor Deduct	0.0%		
				ŝ	Subcontractor Deduct			
Subsolai Esrupin	est Penal		er van Heldeledensen en ungezop zo oog og	15	Equipment Rental Deduc	at		*
				The second secon		Deduct Subtota	1	
					No Bond			
CUSTOMER AC		E & AUTHOR HANGE ORI		ROCEED WITH	Total CO Deduct Co	51		***************************************
					or property and the second		·p.········	***************************************
					Chanana Andre Y.A.			
					Change Order Tota	ts:	\$	2,435.33

12 THHN CU STRANDED	283.5	\$102.90	M	1000	\$29.17	9 M	1000	2.55
14/2 NM-B ROMEX W/GRD CABLE	3	\$230.23	M	1000	\$0.69	45 M	1000	0.14
ROMEX CONNECTOR 3/8" 2 SCREW	3	\$46.94	C	0100	\$1.41	0.15 €	0001	0.45
1 ROMEX STAPLE	3	\$21.50	M	1000	\$0.06	0 X	0000	0
3/4 EMT	90	\$37.43	\in	0100	\$33.69	7.5 C	0100	6.75
3/4 EMT CONN D/S	à	582.25	C	0100	\$7.40	0.15 €	0001	1.35
3/4 EMT COUP D/S	9	\$86.78	C	0100	\$7.81	0.07 E	0001	0.63
3/4 EMT 1 HOLE STP/STL	11.25	\$36.17	C	0100	\$4.07	6 C	0100	0.68
10 X 1-1/2 COMB PAN HD TAP SCR	11.25	\$3.38	C	0100	\$0.38	9 C	0100	1.01
1/4 FLAT STEEL WASHER	11.25	\$72.90	C	0100	\$8.20	1.09 C	0100	0.12
Tan 3M WIRE NUT	6	\$8.42	C	0100	\$0.50	0 C	0100	0
BUCHANAN 20065 4-#12 CU CRIMP CONN	3	\$10.70	C	0100	\$0.32	0.0	0100	0
REC. CAN 4" SMALLING.	3	\$0.00	O	0000	\$0.00	1 95 F	0001	5.85

\$93.70 19.53

SERIES 2040-01/07 ALUMINUM FRAME

isolite





SELF-LUMINOUS EXIT SIGN


- · Requires no electricity or external light source
- · Maintenance free no lamps or batteries to replace
- Easy to install no wiring required
- · Ideal for damp, wet and explosion proof applications
- · Ideal for extreme temperatures (-67F to 176F)
- Service life 10 or 20 years



Dimensions: 2040-01 Single Face







Specifications

Overall Size: Single Face: $12\frac{1}{2}\frac{1}{2}$ "x $8\frac{1}{2}$ "x $1\frac{1}{2}$ "

Double Face: 12 1/4"x 8 1/4"x 2 1/4

Weight: Single Face: 4 lbs.

Double Face: 8 lbs.

Frame: Extruded aluminum

Stencil: Aluminum stencil

Letters: 6" high; 3/4" stroke, standard exit sign

Arrows: Universal chevrons

Service Life: 10 or 20 years

Approvals: UL Listed to UL 924 Standard, NFPA Life

Safety Code 101

A continuous non-electrical source of illumination

Isolite Self-Luminous Signs are the practical solution for EXIT and safety marking requirements where performance cannot be compromised. These signs are totally self-contained, highly durable and attractive. The Isolite Self-Luminous Signs are illuminated with a light source that consists of glass tubes internally coated with phosphor and filled with tritium gas, a natural isotope of hydrogen. They are completely free of any external energy source providing 10-20 years of continuously illuminated, maintenance-free operation and code compliance.

· Special wording and pictograms available Features:

· Tamper-proof design

• Double face sign utilizes one-piece

construction frame

 Custom colors available Warranty:

Our self-luminous products are warranted against

any defects in material or workmanship for the rated

life of the product.

Ordering Information

Model	Face Color	Service Life	Frame Color	Mounting Brackets	Options
2040-01 Single Face	R = Red G = Green BK - Black	10 = 10 Years 20 = 20 Years	BA = Brushed Aluminum (Standard) BK = Black WH = White	Surface Mount Standard 2040-05 = Single face (ceiling or end)	CW = Custom Wording LX = Lexan Stencil Cover
2040-07 Double Face	BZ = Bronze CC = Custom Color		BZ = Bronze CC = Custom Color	2040-10 = Double face (ceiling or end)	
				PA = 12" Swivel Pendant PB = 24" Swivel Pendant	
				PC = 36" Swivel Pendant	
				PD = 48° Swivel Pendant	

Example: 2040 on-R-to BK

Tralleg Number.



all the Isolic office nearest you.

HEADQUARTERS (Waterpal Actor)

WESTERN OFFICE 156 ; Suelda, Suite M han i silibispo, ce per



Alternates LFUCG Replacement Senior Critzen Center Lexington, KY

6/28/2014. 4/43 /164

ig Owner Approval Furnish and Install a Closure Door at the Security Grille at the Reception Desk per Prop	Quantity Units Hr Raw- osal Request No. 91		atenais isines x Added Belowi — Sub	contractic	1 174. di
Extrash and Install a Closure Door at the Security Grille at the Reception Desk per Proposal Request No. 91 Formish and Install a Closure Door at the Security Grille at the Reception Desk - U.S. Millwork	1 is	शहर क		27*	
		0	()	275	
	Cost	of In-Place Construction (Lat	oor, Materials and F	quipmenti ::	2
		Mamilia Design and Const	ruction Overhead P	ercentage: "	51.15
		Overhead - Ma	rollia Design and Co	instruction :	
		Mamilia Design and C	Construction Profit P	ercentage -	5.0
		Profit - Ma	mitia Design and Co	nstruction -	
		General Lia	bility Insurance (Cor	nstruction, =	
			Builder's Risk	Insurance =	
	Performance and Payment (3ond (Rate of \$9.40 per \$100	10 of Cost ter \$0 - \$3	5500 Ock ;	55
	Performance and Payment Bond (Ra	te of \$8.15 per \$1000 of Cus	t for \$2,500,000 - \$1	3 : M : 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	t.
	Performance and Payment Bon	d (Rate of \$7.20 per \$1000 o	of Cost for \$5,000 to	X) and un-	
		KY Surcharge on Proje	ct Bonds (1.8% of E	fond Cost:	
		ocał Municipality Tax on Pro	and the same of the same		



Proposal Request Transmittal

eff Archeon, 2019/5/pp. 1. Pet For Lyrian (1997) and Charton etc.

PROJEC.	LFUCG Senior Citizens' Center 201333	0 x 1 75%7	6/22/2016
5 5 £17	Security Grille Closure Door	1986 - 1988 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986 - 1986	PR-091
1 - 4 y	Proposal Request	the state of the state of	01005
· 操作性。	For Review and Response	4	Info Exchange

FROM

Harding Dowell	EOP Architects	सन्तर्वः hdowell@eopa.com	0-105 (859) 231- 7538
TÇ.			
1.84 K	111 A 18		1480 A
Travis Harris	Marrillia Design and Construction	tharris@marrillia.com	

18144

Created by: Harding Dowell

Description:

Please provide pricing to furbish and install a closure door at the face of the pocket that stores the sideways-rolling security grille at the Reception desk. The door shall be approx. 3.4. agrifiber board with white melamine facing on all faces and edges. The door shall be provided with a continuous plane hinge on the south edge (such that the door swings to the south); the hinge shall be a brushed chapter finish. The door shall be fitted with a magnetic catch, push the open bush to secure, hardware, with no exposed fasteness of paraware and matter shall be mendionated with unite door and countered in craftation.

eropesa Request hansmittat 6/22/2016 01005

Thanks,

Harding

COMPLE

Brian Gravitt	(Marrillia Design and Construction)
Jim Martin	(Marrillia Design and Construction)
Josh Marrillia	(Marrillia Design and Construction)
Rob Price	(Marrillia Design and Construction)
Jessica Walker	(LFUCG)
Joyce Thomas	(LFUCG)
Martin Woodford	(LFUCG)

Travis Harris

From:

Dennis Wetzel < dennis@usmillwork.com>

Sent:

Monday, June 27, 2016 3:45 PM

To: Cc: Travis Harris Jim Martin

Subject:

RE: Transmittal_ProposalRequest - PR-091 (Sent and Closed).pdf

U.S. MILLWORK, INC.

CASEWORE FOR COMMERCIAL APPLICATIONS

Response to Proposal Request 091

From: US Millwork, Inc. D. Wetzel 4815 Allmond Ave.

Louisville, KY 40214

To: TRAVIS HARRIS - MARRILLIA LEXINGTON SENIOR CENTER 195 LIFE LANE LEXINGTON, KY 40502

Date: 27.June.2016

We are sending you the following response to PR 091:

No	Question	Answer
1	Quote requested for closure door at rolling security grille at Reception area.	\$275.00 However, rolling security grille does not seem to fit so well into pocket. Lots of damage to GWB edges probable with daily use of grille. USMill suggests revisit of closure door design with possible wood or metal trim around face of opening, which this quote does not reflect.

For review and comment.

Dennis Wetzel

Project Manager US Millwork, Inc. 4815 Allmond Ave Louisville, KY 40014 502) 587-9450

From: Travis Barris phailte:thannsiquiarmila.com

Sent: Thursday, Jacke 23, 2016 9 25 AND

To: Dennis Morror

Cc: Jim Martin; Brian Gravitt

Subject: Transmittal_ProposalRequest - PR-091 (Sent and Closed).pdf

Dennis,

Please see the attached PR requesting pricing on the door to hide the grill door at the receptionist desk. You will need to field measure this after Bennetts fixes the drywall so the gill door is not rubbing the GWB.

Thanks,

Travis Harris

Site Manager
Marrillia Design and Construction
259 West Short Street, Suite 325
Lexington, Kentucky 40507
Tel 859.685.0414
Fax 859.685.0418
Cell 859.200.9732
Web www.marrillia.com
Email tharris@marrillia.com



zubmit Spam

Travis Harris

From:

Dennis Wetzel <dennis@usmillwork.com>

Sent:

Monday, June 27, 2016 3:45 PM

To:

Travis Harris
Jim Martin

Cc: Subject:

RE: Transmittal_ProposalRequest - PR-091 (Sent and Closed).pdf

U.S. MILLWORK, INC.

CASEWORK FOR COMMERCIAL APPLICATIONS

Response to Proposal Request 091

From: US Millwork, Inc. D. Wetzel

4815 Allmond Ave. Louisville, KY 40214 To:

TRAVIS HARRIS - MARRILLIA LEXINGTON SENIOR CENTER 195 LIFE LANE

LEXINGTON, KY 40502

Date: 27.June.2016

We are sending you the following response to PR 091:

No	Question	Answer
4	Quote requested for closure door at rolling security grille at Reception area.	\$275.00 However, rolling security grille does not seem to fit so well into pocket. Lots of damage to GWB edges probable with daily use of grille. USMill suggests revisit of closure door design with possible wood or metal trim around face of opening, which this quote does not reflect.

For review and comment.

Dennis Wetzel

Project Manager US Millwork, Inc. 4815 Allmond Ave. Louisville, KY 40214 5021 587-9450

From: Travis Hand (mailto:thanis)/maniiba com,

Sent: Thursday, June 13, 2016 9.31 AM

To: Donn's Webs.

Cc: Jim Martin; Brian Gravitt

Subject: Transmittal_ProposalRequest - PR-091 (Sent and Closed).pdf

Dennis,

Please see the attached PR requesting pricing on the door to hide the grill door at the receptionist desk. You will need to field measure this after Bennetts fixes the drywall so the gill door is not rubbing the GWB.

Thanks,

Travis Harris

Site Manager
Marrillia Design and Construction
259 West Short Street, Suite 325
Lexington, Kentucky 40507
Tel 859.685.0414
Fax 859.685.0418
Cell 859.200 9732
Web www.marrillia.com



Sulawa Spare