

Billing Address

Lexington-Fayette/LFUCG 200 E Main Street Lexington, KY 40507 UNITED STATES **Delivery Address**

Town Branch WWTP 301 Jimmie Campbell Drive Lexington, KY 40504 UNITED STATES

OFFER:

C1002028 / V1

Your Reference:

Lexington, KY 286229

Your Reference: (3)286229_294100_SSF-HE 5000X1026X6

(2) 286229_292100_WAP/2 V2A

Date printed:

10/27/25

Our Reference:

David Abernathy

Phone:

Email:

David.Abernathy@hhusa.net

Customer No.:

114516

This proposal has been prepared following the on-site visits and evaluations carried out by our HUBER Service Advisor, Jay Byrnes. The scope of the proposed items are based on the current needs for complete rebuilds of the unit. This offer is intended to be a complete package aiming to reduce downtime while supporting the long term realability and availability of your system.

Pos	Quantity	Unit	Item Description	Price USD	Total USD Tax (%)
10/1	59.00	pcs	PARTS FOR SSF STEPSCREEN UNIT 1 505307 lamella doubling SSF/6 t2 L252 W122 H6	36.37	2,145.83 0%
20/1	100.00	pair	505224 spacer SS#6 t2 T5,8-5,9	2.58	258.00 0%
30/1	3.00	pcs	700501 flange bearing RVFW 50 S	136.38	409.14 0%
31/1	8.00	pcs	702683 hexagon bolt DIN 933 M12x 40	2.07	16.56 0%
32/1	8.00	pcs	702839 hexagon nut DIN 934 M12	1.50	12.00 0%
33/1	8.00	pcs	702426 washer DIN 125 A13,0	0.64	5.12 0%
34/1	2.00	pcs	702330 retaining ring DIN 471 50x2,00	12.86	25.72 0%

HUBER Technology, Inc. 1009 Airlie Parkway • Denver, NC 28037

Phone (704) 949-1010 • Fax (704) 949-1020 • huber@hhusa.net • www.huber-technology.com



C1002028

Date printed:

10/27/25

0%

0%

13.80

0.46

				Page:	2 (12)	
Pos	Quantity	Unit	Item Description		Price USD	Total USD Tax (%)
35/1	4.00	pcs	703480 countersunk screw ISO 10642 M12x 45		1.35	5.40 0%
36/1	4.00	pcs	702839 hexagon nut DIN 934 M12		1.50	6.00 0%
37/1	4.00	pcs	702426 washer DIN 125 A13,0		0.64	2.56 0%
40/1	2.00	pcs	504427 eccenter SSF 90x50x138,5 50h7/50H7		1,255.95	2,511.90 0%
50/1	2.00	pcs	709602 feather key DIN 6885 A14x 9x 63		9.01	18.02 0%
60/1	3.00	pcs	703071 proximity switch M18 IP68 t<40 XS618B1MAL2		239.09	717.27 0%
70/1	3.00	pcs	713252 cable gland M16 WAZU 184.1708 noEx incl. 578.17		3.30	9.90 0%
80/1	8.00	pcs	302903 elbow lever with bush 300x 85x20 H30 bo40		1,120.27	8,962.16 0%
90/1	16.00	pcs	505460 shaft D 40f9/25h9 L40,8 DE28LC		174.86	2,797.76 0%
100/1	32.00	pcs	52112744 sleeve 10,5/ 19,05x 31		12.73	407.36 0%
110/1	8.00	pcs	52112727 plate 150x 60x 6,35 2xbo7		58.56	468.48 0%
130/1	1.00	pcs	10109720 Kluber Paste 70g Tube		41.85	41.85 0%
140/2	1.00	pcs	10065666 LOCTITE 648 Kit		140.99	140.99 0%
160/1	18.00	pcs	PARTS FOR WASHPRESS UNIT 1 708616 set screw DIN 914 M 5x 6		0.23	4.14 0%
170/1	3.00	wdg	704093 strip brush D 222 d 170 d0,60 W 8 h10 BL16 H26		83.58	250.74 0%
171/1	1.00	pcs	506675 sleeve 110H8/140x 47		1,253.63	1,253.63 0%
180/1	6.00	pcs	501813 wear bar 30/ 6x 320		284.30	1,705.80 0%
190/1	30.00	pcs	706938		1.23	36.90

HUBER Technology, Inc.
1009 Airlie Parkway • Denver, NC 28037

Phone (704) 949-1010 • Fax (704) 949-1020 • huber@hhusa.net • www.huber-technology.com

cap screw DIN 912 M10x 12

washer DIN 125 A10,5

702425

200/1 30.00

pcs



C1002028

Date printed:

10/27/25

				Page:	10/27/25 3 (12)	
Pos	Quantity	Unit	Item Description		Price USD	Total USD Tax (%)
210/1	4.50	m	703533 edge protection profile s 8 t2,0-5,0		27.02	121.59 0%
220/1	1.00	pcs	702012 flat jet nozzle JCQ2310 3/8" 60° 3 bar: 31 l/min		30.86	30.86 0%
230/1	1.00	pcs	713955 spherical roller bearing 22313EXQW33 d 65 D140 W	/48	336.87	336.87 0%
240/1	2.00	pcs	702333 Nilos sealing ring 22313 JV CrNi d77,5 D140		59.14	118.28 0%
250/1	1.00	pcs	702338 grooved ring 90/110x12		267.44	267.44 0%
260/1	1.80	m	10451562 edge protection profile s13,46 t0,79-3,94		24.32	43.78 0%
280/1	1.00	pcs	10109720 Kluber Paste 70g Tube		41.85	41.85 0%
290/1	1.00	pcs	10065666 LOCTITE 648 Kit		140.99	140.99 0%
295/1	1.00	pcs	10000002 Hardox welding rods		200.00	200.00 0%
300/1	59.00	pcs	PARTS FOR SSF STEPSCREEN UNIT 2 505307 lamella doubling SSF/6 t2 L252 W122 H6		36.37	2,145.83 0%
310/1	100.00	pair	505224 spacer SS#6 t2 T5,8-5,9		2.58	258.00 0%
320/1	3.00	pcs	700501 flange bearing RVFW 50 S		136.38	409.14 0%
330/1	8.00	pcs	702683 hexagon bolt DIN 933 M12x 40		2.07	16.56 0%
340/1	8.00	pcs	702839 hexagon nut DIN 934 M12		1.50	12.00 0%
350/1	8.00	pcs	702426 washer DIN 125 A13,0		0.64	5.12 0%
360/1	2.00	pcs	702330 retaining ring DIN 471 50x2,00		12.86	25.72 0%
370/1	4.00	pcs	703480 countersunk screw ISO 10642 M12x 45		1.35	5.40 0%
380/1	4.00	pcs	702839 hexagon nut DIN 934 M12		1.50	6.00 0%
390/1	4.00	pcs	702426 washer DIN 125 A13,0		0.64	2.56 0%

HUBER Technology, Inc.
1009 Airlie Parkway • Denver, NC 28037
Phone (704) 949-1010 • Fax (704) 949-1020 • huber@hhusa.net • www.huber-technology.com



C1002028

Date printed:

10/27/25

Date printed.	10/21/1
Page:	4 (12)

Pos	Quantity	Unit	Item Description	Price USD	Total USD Tax (%)
400/1	2.00	pcs	504427 eccenter SSF 90x50x138,5 50h7/50H7	1,255.95	2,511.90 0%
410/1	2.00	pcs	709602 feather key DIN 6885 A14x 9x 63	9.01	18.02 0%
420/1	3.00	pcs	703071 proximity switch M18 IP68 t<40 XS618B1MAL2	239.09	717.27 0%
430/1	3.00	pcs	713252 cable gland M16 WAZU 184.1708 noEx incl. 578.17	3.30	9.90 0%
440/1	8.00	pcs	302903 elbow lever with bush 300x 85x20 H30 bo40	1,120.27	8,962.16 0%
450/1	16.00	pcs	505460 shaft D 40f9/25h9 L40,8 DE28LC	174.86	2,797.76 0%
460/1	32.00	pcs	52112744 sleeve 10,5/ 19,05x 31	12.73	407.36 0%
461/1	8.00	pcs	52112727 plate 150x 60x 6,35 2xbo7	58.56	468.48 0%
480/1	1.00	pcs	10109720 Kluber Paste 70g Tube	41.85	41.85 0%
490/1	1.00	pcs	10065666 LOCTITE 648 Kit	140.99	140.99 0%
500/1	18.00	pcs	PARTS FOR WASHPRESS UNIT 2 708616 set screw DIN 914 M 5x 6	0.23	4.14 0%
510/1	3.00	wdg	704093 strip brush D 222 d 170 d0,60 W 8 h10 BL16 H26	83.58	250.74 0%
520/1	1.00	pcs	506675 sleeve 110H8/140x 47	1,253.63	1,253.63 0%
530/1	6.00	pcs	501813 wear bar 30/ 6x 320	284.30	1,705.80 0%
540/1	30.00	pcs	706938 cap screw DIN 912 M10x 12	1.23	36.90 0%
550/1	30.00	pcs	702425 washer DIN 125 A10,5	0.46	13.80 0%
560/1	4.50	m	703533 edge protection profile s 8 t2,0-5,0	27.02	121.59 0%
570/1	1.00	pcs	702012 flat jet nozzle JCQ2310 3/8" 60° 3 bar: 31 l/min	30.86	30.86 0%
580/1	1.00	pcs	713955 spherical roller bearing 22313EXQW33 d 65 D140 W48	336.87	336.87 0%

HUBER Technology, Inc. 1009 Airlie Parkway • Denver, NC 28037

Phone (704) 949-1010 • Fax (704) 949-1020 • huber@hhusa.net • www.huber-technology.com



C1002028

Date printed:

10/27/25

0%

9.90

0%

3.30

				Page:	5 (12)	
Pos	Quantity	Unit	Item Description		Price USD	Total USD Tax (%)
590/1	2.00	pcs	702333 Nilos sealing ring 22313 JV CrNi d77,5 D140		59.14	118.28 0%
600/1	1.00	pcs	702338 grooved ring 90/110x12		267.44	267.44 0%
710/1	1.80	m	10451562 edge protection profile s13,46 t0,79-3,94		24.32	43.78 0%
730/1	1.00	pcs	10109720 Kluber Paste 70g Tube		41.85	41.85 0%
740/1	1.00	pcs	10000002 Hardox welding rods		200.00	200.00 0%
750/1	59.00	pcs	PARTS FOR SSF STEPSCREEN UNIT 3 505307 lamella doubling SSF/6 t2 L252 W122 H6		36.37	2,145.83 0%
760/1	100.00	pair	505224 spacer SS#6 t2 T5,8-5,9		2.58	258.00 0%
770/1	3.00	pcs	700501 flange bearing RVFW 50 S		136.38	409.14 0%
780/1	8.00	pcs	702683 hexagon bolt DIN 933 M12x 40		2.07	16.56 0%
790/1	8.00	pcs	702839 hexagon nut DIN 934 M12		1.50	12.00 0%
800/1	8.00	pcs	702426 washer DIN 125 A13,0		0.64	5.12 0%
810/1	2.00	pcs	702330 retaining ring DIN 471 50x2,00		12.86	25.72 0%
820/1	4.00	pcs	703480 countersunk screw ISO 10642 M12x 45		1.35	5.40 0%
830/1	4.00	pcs	702839 hexagon nut DIN 934 M12		1.50	6.00 0%
840/1	4.00	pcs	702426 washer DIN 125 A13,0		0.64	2.56 0%
850/1	2.00	pcs	504427 eccenter SSF 90x50x138,5 50h7/50H7		1,255.95	2,511.90 0%
860/1	2.00	pcs	709602 feather key DIN 6885 A14x 9x 63		9.01	18.02 0%
870/1	3.00	pcs	703071		239.09	717.27

HUBER Technology, Inc.
1009 Airlie Parkway • Denver, NC 28037
Phone (704) 949-1010 • Fax (704) 949-1020 • huber@hhusa.net • www.huber-technology.com

M18 IP68 t<40 XS618B1MAL2

cable gland M16 WAZU 184.1708 noEx incl. 578.17

proximity switch

713252

880/1 3.00

pcs



Page:

C1002028

Date printed:

10/27/25 6 (12)

			i age.	0 (12)	
Pos	Quantity	Unit	Item Description	Price USD	Total USD Tax (%)
890/1	8.00	pcs	302903 elbow lever with bush 300x 85x20 H30 bo40	1,120.27	8,962.16 0%
900/1	16.00	pcs	505460 shaft D 40f9/25h9 L40,8 DE28LC	174.86	2,797.76 0%
910/1	32.00	pcs	52112744 sleeve 10,5/ 19,05x 31	12.73	407.36 0%
920/1	8.00	pcs	52112727 plate 150x 60x 6,35 2xbo7	58.56	468.48 0%
940/1	1.00	pcs	10109720 Kluber Paste 70g Tube	41.85	41.85 0%
950/1	1.00	pcs	10065666 LOCTITE 648 Kit	140.99	140.99 0%
960/1	1.00	pcs	10000002 Estimated freight & import duties	3,400.00	3,400.00 0%
970/1	1.00	pcs	SERVICE FOR REBUILD & WAP INSTALL 10000002 Labor for rebuilds tech 1	22,907.16	22,907.16 0%
980/1	1.00	pcs	10000002 Labor for rebuilds tech 2	22,907.00	22,907.00 0%
990/1	1.00	pcs	10000002 Labor for New WASHPRESS install tech 1	4,268.00	4,268.00 0%
1000/1	1.00	pcs	10000002 Labor for New WASHPRESS install tech 2	4,268.00	4,268.00 0%
			Total net	USD	123,628.57
			Including Sales Tax Total gross	USD	0.00 123,628.57

Additional tariffs, import duties, or other government-imposed charges introduced after a quote or order has been placed are not included in our pricing and will be invoiced separately to the customer. HUBER Technology Inc. will inform customers of relevant changes to the best of our knowledge and economic feasibility.

The quotation is subject to national or international export control regulations and embargoes or any other export restrictions.

Valid for:

30 days

Delivery:

prepaid and add

Payment terms: Net 30 days

Best regards



Offer: C1002028Date printed: 10/27/25

Page: 7 (12)

David Abernathy

Huber Technology, Inc.



C1002028

Date printed:

10/27/25

Page:

8 (12)

Aftermarket Sales & Service Rates 2025

Field Service Base Rate	\$170.00 per hour
Training Product Training	\$170 00 per hour
Product Training Travel	\$170.00 per nour
Travel (time)	. \$170.00 per hour
Mileage	
Manufacturing/Engineering Services in house	
Services include failure analysis of returned hardware	\$170.00 per hour
Premium Rates	
Premium Rates Overtime rate (in excess of 8 hours per day	\$240.00 per hour
	•
Overtime rate (in excess of 8 hours per day	Applicable base rate
Overtime rate (in excess of 8 hours per day	Applicable base rate \$340.00 per hour
Overtime rate (in excess of 8 hours per day	Applicable base rate \$340.00 per hour
Overtime rate (in excess of 8 hours per day	Applicable base rate \$340.00 per hour Actual cost
Overtime rate (in excess of 8 hours per day	Applicable base rate \$340.00 per hour Actual cost



Offer: C1002028 10/27/25 Date printed: 9 (12)

Page:

Aftermarket Sales & Service Rates 2025

Field service Base Rate. Rates are calculated from the day the Service Specialist departs Huber Technology, Huntersville, North Carolina until the day the Service Specialist returns to Huber Technology, Inc., Huntersville, North Carolina. Rates include weekends and holidays. If a Service Specialist is required to travel from any other location, including, Germany the rates are calculated from when the Service Specialist departs the home office until the day the Service Specialist returns to the home office.

Travel. Time includes transportation to and from the airport, security clearance, time between flight changes, driving time and local travel to and from worksite. Travel time in excess of eight (8) hours may be billed at the premium rate. <u>Double Time.</u> Any Sunday or Recognized Huber Technology, Inc. Holiday. **Transportation.** The customer is responsible for reimbursing Huber Technology. Inc. for all transportation charges associated with service work. Flights will be booked as coach-tourist class unless it is unavailable. Rental car, gas, taxis, airport / hotel limousines, company or personal vehicles will be used when necessary. Standby rate. Applies to the time a Service Specialist is available for work and is located at or near the job site but unable to work due to circumstances beyond his control. Time shall be considered time worked and will be charged at the applicable base or premium rate.

Accommodations and Meals. Meals are charged at \$60.00 per day or \$70.00 per living accommodations and meals will be invoiced. Invoices day depending on the area (See Business Rate Plan 1 and 2). If an overnight stay is required, the customer is required to reimburse Huber Technology, Inc. for lodging charges. Hotel rooms will be booked on a business executive, single occupancy basis.

Visa, Work Permits & Local Taxes. The customer is responsible to pay any and all taxes, user fees or special assessments. If a visa or work permit is required before departing for an international assignment, the fee will be charged to the customer at actual cost (including any expediting charges).

Warranties. Per Huber Technology, Inc.'s Terms and Conditions of Sale, Huber Technology, Inc. warrants Field Service work performed at site. "Breach of Warranty" service arrangements will be made. The purchase order is to be made out claims do not entitle the customer to refuse payment for field service work. HUBER TECHNOLOGY, INC. MAKES NO OTHER WARRANTY, EXPRESS OR IMPLIED, WITH REGARD TO THE DESIGN, SALE, MERCHANTABILITY OR FITNESS OF THE GOODS FOR A PARTICULAR PURPOSE OR USE EXCEPT AS commissioning, troubleshooting, training, etc.), 6) serial number EXPRESSLY SET FORTH IN HUBER TECHNOLOGY, INC.'S TERMS AND CONDITIONS, HUBER TECHNOLOGY, INC. IS NOT SUBJECT TO ANY OTHER OBLIGATIONS OR LIABILITIES ARISING OUT OF BREACH OF CONTRACT OR WARRANTY, TORT CLAIMS INCLUDING NEGLIGENCE AND STRICT LIABILITY, city, state, plant site, directions to the site, a local contact and OR ANY OTHER THEORIES OF LAW. HUBER TECHNOLOGY, INC. IS UNDER NO EVENT LIABLE FOR ANY SPECIFIC, INDIRECT, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGES, EXPENSE, INJURY, DISMEMBERMENT, OR DEATH OF ANY KIND WHATSOEVER.

SCHEDULING - 10 Working Days Notice. Request for field service should be made in writing (letter, fax or e-mail) to Huber Technology, Inc. at least ten (10) working days prior to the date for which services are requested. Confirmation of the service will be conveyed verbally by Huber Technology, Inc.

Insurance. All Huber Technology, Inc. Service Specialists are insured. Liability insurance certificates may be provided upon request by the customer in order to allow for sufficient time for document processing, the request must be made at least seven (7) working days prior to the date of services.

Hazardous Locations.

Huber Technology, Inc. reserves the right to recall its personnel if the worksite does not meet governmental health and safety standards. Minimum Daily Charge. For all Field Service Base Rates or combinations of Base Rates, the minimum fee will be for eight (8) hours. If services are performed on the same day as travel, travel time will be billed in addition to service time.

Overtime. The overtime rate applies to work or travel in excess of eight (8) hours per day (weekdays) and all Saturday work. Workdays in excess of (16) hours are prohibited. Service specialist are NOT required to perform, and may decline, work in excess of twelve (12) hours. The overtime charge shall be at the base rate plus a one hundred percent (100%) premium.

Recognized Huber Technology, Inc. Holidays New Year's Day, Good Friday, Memorial Day, Independence Day, Labor Day, Thanksgiving Day, the Friday after Thanksgiving Day, Christmas Eve and Christmas Day. **Expenses.** The customer is responsible for ALL expenses associated with service work. All travel expenses including airfare, taxi, mileage for personal or company owned vehicles or any other chauffeured vehicle. will include a cost

break-down. Copies of receipts will not be furnished unless specifically requested. Original receipts cannot be provided. Receipts for under \$25.00 cannot be provided. Use of personal or company owned vehicles will be invoice at the rate set by IRS mileage regulations.

Payment. All field service invoices are in U.S. Currency and all payments must be in U.S. Dollars. Payment is due NET 30 DAYS from the date of invoice.

Purchase Orders. A purchase order is required BEFORE any field to Huber Technology, Inc. and must contain the following information: 1) Customer's name, 2) company, 3) billing address, 4) dates of service, 5) type of service requested (i.e. installation, / model number, 7) equipment purchase order number, and 8) equipment tag numbers. A "confirming-copy" purchase order must follow any preliminary arrangements. Equipment location including telephone number must also be included.

2) Amended Purchase Orders. An amended PO is required if services are extended beyond the cost of the original PO. If the Service Specialist is on site and an amendment is required, the PO must be completed and submitted to Huber Technology, Inc. before the Service Specialist can continue working.

Applicable law. Any purchase order accepted by Huber Technology, Inc. in conjunction with Field Service work, shall be deemed to have been executed, delivered and accepted in the State of North Carolina, USA and shall be governed, construed and enforced pursuant to the laws of the State of North Carolina, USA

Huber Technology, Inc. can not offer fixed lump sum contracts for Field Service activities. The duration of site visitation is neither under our direct control nor influence, and as such we can only provide estimates of time on-site to affect the required service actions. Field service published rates and terms are valid through December 2025



C1002028 10/27/25

Offer:
Date printed:

Page: 10 (12)

Warranty and Returns Policy & Instructions

Huber Technology, Inc. ("Huber") warranties any **original** Huber part (mechanical or electrical) for a period of:

A. Twelve (12) months from the date of purchase and only when part(s) are installed by a Huber factory trained technician. Should the part(s) fail within the warranty period, a replacement shall be supplied at no cost to the owner ("Replacement Part")

- 1. Only valid if the product is operated in accordance with the manufacturer's instructions.
- 2. The replacement part(s) must not be modified or changed in anyway.
- 3. The replacement part(s) must be installed by a qualified person to the manufacturer's specifications Or
- B. Three (3) months from the date of purchase and/or installed by a non-Huber factory trained technician.
- 1. Only valid if the product is operated in accordance with the manufacturer's instructions
- 2. The replacement part(s) must not be modified or changed in anyway.
- 3. The replacement part(s) must be installed by a qualified person to the manufacturer's specifications

This warranty does not apply to any damage or defect arising out of any of the following circumstances:

- Part(s) needing repair or replacement due to events or circumstances outside of normal use and operation of the equipment.
- Part(s) or components damaged due to power surges, short circuits, loss of power, lightning strikes, fire or water damage, vandalism, theft, or any other causes outside of normal use and operation of the equipment or that would normally be covered by casualty insurance on the equipment.
- Damage or defects caused by neglect, incorrect application, abuse, or by accidental damage of the parts or components.
- Repair or replacement of part(s) or components due to improper or negligent operation of the equipment.
- Damage or defects to the part(s), component(s), or equipment caused by the attempted repair by an unauthorized or unqualified person.

All Huber parts warranties are non-transferable, and cannot be sold, assigned or transferred in any other way.

This warranty of **original** Huber Service parts does not include the labor to remove the defective part nor the labor to install the new part. **All labor costs associated with the replacement of the part is the responsibility of the owner.** The request for assistance of a certified Huber technician is available upon the issuance of a purchase order by the owner. The fee for the assistance of a Huber technician includes labor (billed at prevailing Huber Field Service Base Rates) plus associated expenses for travel to and from the jobsite.

Return of New Wear or Spare Parts:

- Any original Huber part(s) returned to Huber after a purchase order has been submitted is subject to a flat twenty percent (20%) restocking fee for each part returned.
- The customer has up to thirty (30) days to return a part from the purchase order submittal date to Huber. Returns will not be accepted past thirty (30) days.
- Part(s) must be new and never installed. Any indication of wear or installation, at Huber's sole discretion, may result in the part(s) being shipped back to owner, at the owner's cost, and no credit shall be issued.

• Exception:

The owner may exchange, without a restocking fee, if the incorrect part(s) is delivered and/or sold to the



 Offer:
 C1002028

 Date printed:
 10/27/25

Page:

11 (12)

owner by a Huber team member. Huber will ship the correct part(s) to the owner expeditiously. A refund will be issued to the owner upon Huber's receipt of the incorrect part(s).

The customer may return, without a restocking fee, any original Huber part(s) if said part(s) was sold as part of a complete rebuild and the Huber technician concluded the part(s) were not needed. The customer has thirty (30) days from the date the service was completed. After thirty (30) days have expired, the normal Huber restocking fee shall apply.



C1002028

Date printed:

10/27/25

Page:

12 (12)

Warranty and Returns Policy & Instructions

Return of Damaged / Defective Items

- In the event of a damaged or defective part, the return process can often be expedited by providing a digital image of the damage or defect (along with a clear description of the problem) in an email to the Huber Aftermarket Team ("Aftermarket Team") at the following email address: returns@hhusa.net. The phone and fax numbers for Aftermarket Team are: 704.990.2045; Fax: 704.896.2830. Huber reserves the right to inspect in person even if a digital image is provided as outlined above.
- If the damage or defect **cannot be verified over the phone or via email** contact, the item may be required to be returned to Huber Technology, Inc. for inspection before a determination can be made as to the state of the product.
- The Aftermarket Team will validate the warranty claim for the defective part.
- If the Aftermarket Team determines that the part is under warranty and should be replaced, the Aftermarket Team will provide a Return Merchandise Authorization ("RMA") number and a shipping address to the Customer for the return of the defective part.
- The Customer shall ship the part to the specified address with the RMA number listed on the outside of the package.
- When the warranty part has been repaired (or replaced) by Huber, the part will be shipped to the "ship-to" address included in the RMA information provided by the Customer.

Return shipping cost

- ONLY in the event that an incorrect part is sold to the Customer by a Huber team member, will Huber pay for shipping. The Customer will be provided with a prepaid return shipping label.
- UNDER ALL OTHER CIRCUMSTANCES, the Customer returning the part(s) is responsible for any freight costs incurred for returning the part(s).
- UNDER NO CIRCUMSTANCE will Huber reimburse (or provide credit) for return shipping costs incurred by the Customer.

How to Request an RMA (Return Merchandise Authorization)

Contact the Huber Technology Aftermarket Sales Team and request a Return Merchandise Authorization ("RMA") number.

- · Completely fill out the RMA form.
- Include the completed RMA form in the package along with the item(s) to be returned.
- Write the RMA number conspicuously on the outside of the package to ensure proper routing upon receipt by the Aftermarket Team.
- · Ship the package to:

o o Huber Technology, Inc. Aftermarket Sales and Service 1009 Airlie Parkway Denver, NC 28037

Phone: 704.874.8237 Fax 704.896.2830 Email: service@hhusa.net